



Business & Financial Services Department
Telephone: 604-276-4097
Fax: 604-276-4162

June 14, 2010
File: 02-0775-50-3922/Vol 01

Dear Sir/ Madame,

Re: Addendum #4 T.3922 Watermain Replacement Program 2010 Lulu East and West

The following change is hereby made a part of the Quote Documents as fully and wholly as if the same were fully set for the therein:

1. Questions & Answers

Q1. Dwg No. WC-957 Gilley Road Watermain: From Sta. 0+93 to Sta. 3+09 the watermain is along the centreline, how is the restoration bylaw going to apply (lane restoration or 2 lane restoration) or as per typical cross section?

A1) This section of Gilley Road is a bus route and so therefore bylaw 7869 applies. If two lanes are affected by the trench, then both lanes will need to be restored as per bylaw 7869.

Q2. Dwg No. WC-957 Gilley Road Watermain: From Sta. 3+09 to Sta. 5+2, the watermain is along the west bound lane, how is the restoration bylaw 7869 going to apply (centreline to gutterline)? Or as per typical cross section.

A2. Bylaw 7869 does not apply as this section of Gilley Road is a local road with no bus route.

Q3. Are we allowed to use C900 DRI8 PVC pipe c/w joint restraints in lieu of C900/RJ COBT lock pipe?

A3. Yes, this substitution is acceptable, and must be fully restrained.

Q4. DWG. WC-95B No.8 Road Watermain: The watermain is along the east side of No. 8 Toad, how is the restoration bylaw 7869 going to apply (from edge to centreline) or as per typical gross section?

A4. Bylaw 7869 does not apply as this is not an arterial nor collector, nor bus route.

Q5. DWG. WC-962 Corless Road Watermain: Note #10 Conflicting (joints restraints as per table. Are joints to be restrained?

A5. All joints shown on this drawing must be restrained.

Q6. DWG. WC-964 St. Albans – Francis to Blundell: Typical section (Francis to Lucerne) shows 35mm grind tack cost & o/l but should be 50,, grand tack, o/l.

A6. An addendum will be issued to address this incorrect drawing note.

Q7. DWG WC-961 Seacote Road Watermain Pay Item C.: How do we get paid to provide a 6” service to school (Sta. 2+08)? North of lane.

A7. Was missed in the quantity take-off, will be dealt with in the field.

Q8. Would the above service be upsized to an 8”?

A8. No, size stays at 6".

Q9. DWG WC-993 Lundy Road w/m (sheet 1OF2): #8200/#8100 & #8160/#8140 duplexes says 25mm service c/w meter box, while Std. Note #21 (SHT2OF2) says city to supply and install meter boxes?

A9. Disregard meter note at service. All meters and meter boxes will be installed by City.

Q10. Will there be an extension to the close?

A10. There will not be an extension to the close date.

Yours truly,



S Dosanjh for K.Gillis
Buyer II - Contracting Specialist
City of Richmond